
Service Bulletin

March 24, 1997

MEB97-4

TITLE

FLIGHT IN KNOWN ICING IS PROHIBITED PLACARD INSTALLATION

EFFECTIVITY

<u>Model</u>	<u>Year</u>	<u>Serial Numbers</u>	
310	1955 thru 1957	35000	thru 35546
310A	1957 thru 1958	38000	thru 38161
310B	1957 thru 1958	35547	thru 35549
310B	1957 thru 1958	35551	thru 35771
310B		607	
310C	1959	35772	thru 35999
310C	1959	39001	thru 39031
310C		35550	
310D	1960	39032	thru 39299
310E	1960	310M0001	thru 310M0036
310E		35912A	
310F	1961	310-0001	thru 310-0016
310F	1961	310-0018	thru 310-0156
310G	1962	310G0001	thru 310G0156
310H/E310H	1963	310H0001	thru 310H0148
310I	1964	310I0001	thru 310I0200
310J/310J-1/E310J	1965	310J0001	thru 310J0200
310K	1966	310K0001	thru 310K0245
310L	1967	310L0001	thru 310L0207
310N	1968	310N0001	thru 310N0198
310P/T310P	1969	310P0001	thru 310P0240
310Q/T310Q	1970 thru 1974	310Q0001	thru 310Q1160
310R/T310R	1975 thru 1976	310R0001	thru 310R0735
320/320-1	1962	320-0001	thru 320-0110
320A	1963	320A0001	thru 320A0047
320B	1964	320B0001	thru 320B0062
320C	1965	320C0001	thru 320C0073
320D	1966	320D0001	thru 320D0130
320D		623	
320E	1967	320E0001	thru 320E0110
320F	1968	320F0001	thru 320F0045
320F		658	

Page 1 of 3

To obtain satisfactory results, procedures specified in this publication must be accomplished in accordance with accepted methods and prevailing government regulations. The Cessna Aircraft Company cannot be responsible for the quality of work performed in accomplishing the requirements of this publication.

The Cessna Aircraft Company, Product Support, P.O. Box 7706, Wichita, Kansas 67277, U.S.A. (316) 941-7550, Facsimile (316) 942-9006

COPYRIGHT © 1997

<u>Model</u>	<u>Year</u>	<u>Serial Numbers</u>	
340	1972	340-0001	thru 340-0115
340	1973	340-0151	thru 340-0260
340	1974	340-0301	thru 340-0370
340	1975	340-0501	thru 340-0555
340A	1976	340A0001	thru 340A0125
401	1967 thru 1968	401-0001	thru 401-0322
401A	1969	401A0001	thru 401A0132
401B	1970 thru 1971	401B0001	thru 401B0121
401B	1972	401B0122	thru 401B0221
402	1967 thru 1968	402-0001	thru 402-0322
402A	1969	402A0001	thru 402A0129
402B	1970 thru 1971	402B0001	thru 402B0122
402B	1972	402B0201	thru 402B0249
402B	1973	402B0301	thru 402B0455
402B	1974	402B0501	thru 402B0640
411	1965 thru 1966	411-0001	thru 411-0250
411A	1967 thru 1968	411-0251	thru 411-0300
414	1970	414-0001	thru 414-0099
414	1971	414-0151	thru 414-0175
414	1972	414-0251	thru 414-0280
414	1973	414-0351	thru 414-0437
414	1974	414-0451	thru 414-0550
421	1967 thru 1968	421-0001	thru 421-0200
421A	1969	421A0001	thru 421A0158
421B	1970	421B0001	thru 421B0056
421B	1971	421B0101	thru 421B0147
421B	1972	421B0201	thru 421B0275
421B	1973	421B0301	thru 421B0486
421B	1974	421B0501	thru 421B0665

PURPOSE

To provide a placard to inform the pilot that flight in known icing conditions is prohibited with this airplane. Failure to avoid flight in known icing conditions can result in adverse performance/flight characteristics of the airplane causing the pilot to be unable to maintain altitude which could cause serious injury and/or death to the pilot, crew, and/or passengers.

NOTE: Some airplanes identified in the Effectivity section of this service bulletin may be originally equipped with anti-ice and/or de-ice equipment that could make the airplane appear to be certified for flight in known icing conditions when in actuality it is not.

COMPLIANCE

Mandatory; shall be accomplished within the next 100 hours of operation or 3 months, whichever occurs first.

APPROVAL

FAA approval has been obtained on technical data in this publication that affects airplane type design.

MAN-HOURS

Negligible.

MATERIAL

The following placard is available from Cessna Parts Distribution through an appropriate Cessna Service Station for the suggested list price shown.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Price</u>
DP0500-13	Placard	1	\$ 0.39 (A) ea.

ALL PRICES SUBJECT TO CHANGE WITHOUT NOTICE

ACCOMPLISHMENT INSTRUCTIONS

The DP0500-13 placard is adhesive backed and easy to install, the placard shall be installed on the instrument panel and in clear view of the pilot.

The placard may be installed by the airplane owner or a service facility. After installation of the placard, an entry in the airframe logbook shall be completed to record compliance with this service bulletin.

CREDIT

The DP0500-13 placard is being sent to applicable owners of record at no charge.

OWNER NOTIFICATION

On March 24, 1997, a copy of this service bulletin and the DP0500-13 placard will be sent to applicable owners of record.

* * * * *